

\$1233-21

Tax Invoice: 0010896-D01

Concrete Pumping Equipment Aust. Pty L

Invoice To

Swart & Sons Pty Ltd
PO Box 331

UNLEY SA 5061
ABN: 92 481 903 069

Ship To:

Swart & Sons Pty Ltd

Unit 18 / 543 Churchill Road
KILBURN SA 5084

ABN 42 051 976 482

8 TENNYSON STREET GRANVILLE NSW 2142

PO BOX 19 GRANVILLE 2142

Phone: +61 2 9682 3266

Fax: +61 2 9682 3362

Email: cpe@concretepump.com.au

Web: www.concretepump.com.au



Client Order	A/C No.	Exemption	Your Contact	Sales	Date	Page No.
	1237		Mark	Toni Fletcher	06/12/2010	1

Part No.	Description	Unit	Qty Ord	Qty B/O	Qty Sup	Price (Ex)	Ext. Price	Tax \$	Line T
203509007	STATOR 2L88	Each	1.00		1.00	161.00	161.00	16.10	
422650	ROTOR 2L88	Each	1.00		1.00	320.00	320.00	32.00	

\$1233-21

No returned goods will be accepted in our warehouse without return authorisation number. Goods must be received within 30 days of invoice (except special orders). All returns are subject to a 20% restocking fee or \$50 whichever is the greater.

TERMS OF PAYMENT STRICTLY NET 7 DAYS

All goods are sold subject to the Terms and Conditions of Sale and Contract of CONCRETE PUMPING EQUIPMENT AUST. PTY. LTD and remain their property until fully paid for.

NOTES

Star Track : FHB03281

	Ext Price	GST
Sub Total	481.00	48.10
Courier	0.00	0.00
Freight	21.10	2.11
Freight	0.00	0.00
Invoice Total	502.10	50.21

The total price inclu

WORKSHOP MAINTENANCE FORM

PLANT MAKE	MODEL	DESCRIPTION	YR/MTH
Putzmeister	SV5	Rotor /Stator pump	1989

SERIAL NO	ENGINE NO	ASSET NO
589100780		13

TRAILER REG NO	
----------------	--

3 MONTHLY SERVICE	COMPLETED	SERVICED BY
• Test and Tag		
• Hydraulic drive check oil leaks		
• Visual inspection of all belts		
• .		
•		
•		
•		

END OF PROJECT SERVICE	COMPLETED
• Mixer belt inspection	GW 10/10/11
• Check belts	GW
• Tyre pressure	GW
• Emergency switch box/button (Clean & working)	GW
• MACHINE CLEANED	FM.
•	
•	
•	

NOTES: NEW ROTOR/STATOR INSTALLED 10/10/11

Delivery Docket: 0012363-D01

Concrete Pumping Equipment Aust. Pty Ltd
A.B.N.42 051 976 482

Ship To

Swart & Sons Pty Ltd
Unit 18 / 543 Churchill Road

KILBURN
SA

5084

8 TENNYSON STREET GRANVILLE NSW 2142
PO BOX 19 GRANVILLE 2142

Phone: +61 2 9682 3266
Fax: +61 2 9682 3362
Email: tfletcher@concretepump.com.au
Web: www.concretepump.com.au



Client Order	A/C No.	Exemption	Sales	Date
00311	0089		Ken Fletcher	21/09/2011

Part No.	Description	Ordered	Back Order	Prev Del	This Delivery
211355007	STATOR 2L6	2			2
201111002	ROTOR 2L6	1			1

SS
P 11

Received by (signature): _____ Print Name: _____

Carrier
AAE OVERNIGHT CON NOTE 08243084

TERMS OF SALE STRICTLY NET 7 DAYS

All goods are sold subject to the Terms and Conditions of Sale and Contract of

WORKSHOP MAINTENANCE FORM

PLANT MAKE	MODEL	DESCRIPTION	YR/MTH
Putzmeister	SV5	Rotor /Stator pump	1989

SERIAL NO	ENGINE NO	ASSET NO
589100780		13

TRAILER REG NO	
----------------	--

3 MONTHLY SERVICE	COMPLETED	SERVICED BY
• Hydraulic drive check oil leaks		
• Visual inspection of all belts		
• 1 Stator 2L6 # 211355007	MOB	21.09.11
•	O/n 00311	
•		
•		
•		

END OF PROJECT SERVICE	COMPLETED
• Mixer belt inspection	
• Check belts	
• Tyre pressure	
• Emergency switch box/button (Clean & working)	
•	
•	
•	
•	

NOTES:
Part ordered ex concrete pumping equipment D/D 0012363 Do1

WORKSHOP MAINTENANCE FORM

PLANT MAKE	MODEL	DESCRIPTION	YR/MTH
Putzmeister	SV5	Rotor /Stator pump	1989

SERIAL NO	ENGINE NO	ASSET NO
589100780		13

TRAILER REG NO	
----------------	--

3 MONTHLY SERVICE	COMPLETED	SERVICED BY
• Hydraulic drive check oil leaks	8-9-11	g w
• Visual inspection of all belts	8-9-11	g w
•		
•		
•		
•		
•		

END OF PROJECT SERVICE	COMPLETED
• Mixer belt inspection	g w
• Check belts	g w
• Tyre pressure 30PSI	g w
• Emergency switch box/button (Clean & working)	NO EMERGENCY SWITCH
•	
•	
•	
•	

NOTES: REPLACED HYDRAULIC OIL
TAG - TESTED 8/9/11 (yellow) 334375
INSTALLED BOLT FOR SAFETY GUARD

WORKSHOP MAINTENANCE FORM

PLANT MAKE	MODEL	DESCRIPTION	YR/MTH
Putzmeister	SV5	Rotor /Stator pump	1989

SERIAL NO	ENGINE NO	ASSET NO
589100780		13

TRAILER REG NO	
----------------	--

3 MONTHLY SERVICE	COMPLETED	SERVICED BY
• Hydraulic drive check oil leaks		
• Visual inspection of all belts		
•		
•		
•		
•		
•		

END OF PROJECT SERVICE	COMPLETED
• Mixer belt inspection	
• Check belts	
• Tyre pressure	
• Emergency switch box/button (Clean & working)	
•	
•	
•	
•	

NOTES:	
	<i>Repairs to pump rebit lift legs. July 2011 mu. 651. Prem's brother</i>
	<i>QW.</i>

